

## **Inspection of Nawabganj, Paramat, Babaghat & Guptarghat Dated 21/12/2024 with CE & SE**

### **UPJN.**

#### **Nawabganj IPS 15 MLD:**

##### **DG Set**

- DG repaired but cable connection to utilize it is pending.
- Change over switch burnt to be replaced. IT has not been replaced.

##### **Pump status**

###### **Pump House no 1.**

- Total pumps 3nos (20 HP- 1 no, 40 HP- 2 nos)
- Only one pump sets 20 HP is operational

###### **Pump House no 2.**

- Pump installed 4 nos (40 HP-2nos & 20 HP-2 nos)
- Only One no: 20 HP pump set was operational.

##### **Starters/Panel**

- Starters are not installed on walls and are being used. Panels have been placed but cable connection & commissioned pending.

##### **Electrification**

- Internal and external electrification is insufficient

##### **Maintenance and repair**

- Maintenance is very poor. No painting of pump houses & its repair works have been done.
- Replacement of door/window pending
- Approach road & campus development pending.
- Scrap shifting pending.
- New Exhaust fan are to be installed
- Flow meters are to be installed.
- Ladder and screen to be installed in sump
- Minor boundary wall to be repaired.

##### **Safety issues**

- Operator and sweeper are working without PPE

- During the inspection it was found that there is neither safety arrangement of excavated area and nor covered open sump.

## **Paramath 56 MLD IPS**

### **Pump Status**

#### **Pump House no 1**

- Total pumps 2 nos (each 100 HP)
- Both are operational.

#### **Pump House no 2**

- Total pumps 3 nos (each 125 HP)
- Operational 1 no
- Wrong supply of 2 nos pumps direction of rotation problem./ delivery modification pending.

### **HT panel**

- HT panel bye passed. No protection available.

### **Safety issues**

- Operator and sweeper are working without PPE
- During the inspection it was found that there is neither safety arrangement of excavated area and nor covered open sump.

### **Maintenance and repair**

- Maintenance of civil work very poor. No painting, no cleaning and no repair.
- Internal lightning pending.
- Renovation of DG and DG room pending.
- supply and installation of valves
- Replacement of door/window pending
- Approach road & campus development pending.
- New panels have reached at site they are to be installed properly and commissioning pending.
- Scrap shifting pending.
- New Exhaust fan to be installed
- Flow meters are to be installed.

## **Babaghat 7 MLD IPS**

### **Pump status.**

- Total 3 nos pump. 2 nos of 40 hp & 1 no of 20 hp
- 1 nos 40 hp and 1 no 20 HO pump Operational.
- Other 40 Hp pump casing damage

### **Starters**

- 3 nos starter have not been installed on wall but kept on floor over bricks. New panels have reached at site with starter built in. Proper installation and commissioning pending.

### **D G set**

- Servicing done on 08/01/24 but radiator cleaning is pending. DG set commissioning pending.

### **Safety issues**

- Operator and sweeper are working without PPE
- During the inspection it was found that there open sump not covered properly.

### **Maintenance & repair**

- Exhaust Fans not working .Not replaced.
- Lighting arrangements are very poor
- Mono rail lifting arrangement not repaired/ replaced.
- Boundary Wall damaged to be repaired.
- Repairing of door & window.

## **Guptarghat 3.5 MLD IPS (New 2018)**

### **Pump Status.**

- 4 nos pump of 25 hp each
- 2 nos Operational
- 1 no non operational from 26/04/24

### **Flow meter**

- Not working for last few months

### **HT panel**

- CT/PT problem not rectified for 10 months.
- Maintenance of full panel is required.
- HT panel by passed. No protection available.

### **Maintenance & repair**

- Light fittings Very poor. Fittings not replaced
- DG set non operational from 07/05/24.
- One transformer has not been than connected for more 1 year
- Mechanical screen.2 nos installed but non operational for last 3 months
- Level sensors not working.
- Operator and sweeper are working without PPE.
- Only conduit layed. Wires are to be fixed inside.

### **Note-**

- From inspection it appears that all IPS are neglected and are not attended properly.
- It is serious situation that for attending any defects months/years are taken.
- Safety norms are not followed strictly at all sites sump covers in side pump house were found open for no reason.